

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed : Gwynn Falls

Company : URS

Date : 06/02/2009

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :


Supervisor : Ryan Lamont

Manhole ID : S02QQ1011MH

Test ID : S1032-031010

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND

- SMOKE OBSERVATION
- BLOWER LOCATIONS
- MANHOLE
- SEWER LINE
- SMOKE RUN

| Defect Code | Defect Description |
|-------------|----------------------|
| SL | Service Lateral |
| TJ | Transition Joint |
| DD | Driveway Drain |
| WWD | Window Well Drain |
| STRD | Stairwell Drain |
| AD | Area Drain |
| DS | Downspout |
| DSC | Downspout Connection |
| FD | Foundation Drain |

| Defect Code | Defect Description |
|-------------|--------------------|
| CB | Catch Basin |
| SD | Storm Ditch |
| SWMH | Storm Manhole |
| MAIN | Main Sewer |
| SANMH | Sewer Manhole |
| CO | Cleanout |
| OTHER | Other |
| IOB | Inside of Building |